

**Home Inspections, Inc.**  
6 Highland Avenue  
Queensbury, NY 12804  
518-792-4237



**Site Location:**  
93 Spring Street  
Glens Falls, NY

**Client:**  
Nancy Harper  
12 Oak Street  
Lake George, NY 12866

**Inspection Date:** 5/13/2003

**Job Number:** 152

## Table of Contents

Exterior

Roof

Foundation / Structure

Electrical

Plumbing

Heating / Fireplace

A/C

Kitchen

Bath

Interior / Attic

Wood Boring Insects

Summary

CONFIDENTIAL

# Exterior

The following opinion is based on an inspection of the visible portion of the exterior of the structure. If any conditions are listed a qualified contractor should correct them.

**LANDSCAPING:** Landscaping is inspected only to the degree that it affects the condition of the structure. Examples would be drainage, intruding vegetation, etc.

**Site:** Level

**PAVED AREAS:** This category includes steps and/or stoops, sidewalks, walkways, and/or driveways.

**Driveway:** Asphalt  
**Rating:** Acceptable

**SIDING/TRIM:** Siding refers to the material forming the exterior walls. Masonry construction can perform structural as well as siding functions.

**Siding:** Vinyl  
**Condition:** **Open seam ---** Open seams was noted. All open seams should be caulked and sealed to help prevent water penetrations and damage to the siding.  
Location: at a/c pipe entries  
**Rating:** Maintenance Required

**PATIOS:** Patios add value and enjoyment. Because they are exposed to the weather, they are also higher maintenance items than other portions of the structure.

**Patio:** Concrete  
**Rating:** Acceptable

**WINDOWS:** Windows are an important part of the structure, gaining and losing more heat than any other element.

**Type:** Vinyl  
**Rating:** Acceptable

**Glazing:** Insulated Glass  
**Rating:** Acceptable

**DOORS:** Doors are inspected for functionality and condition. The degree of protection from people or weather is a matter of personal decision.

**Entry:** Metal  
**Rating:** Acceptable

**Other:** Sliding Patio  
**Rating:** Acceptable

**GARAGE:** Standard inspections cover only attached garages and carports. They are not considered habitable, and conditions are reported accordingly.

**Garage:** Attached Garage  
**Rating:** Acceptable

**Cars:** 1

**Doors:** Metal  
**Rating:** Acceptable

**Opener:** Automatic  
**Rating:** Acceptable

**FIRE DOOR:** Fire doors are inspected for their safety aspects only in this section.

**Type:** Metal  
**Rating:** Acceptable

CONFIDENTIAL

# Roof

This report is made on the basis of what was visible and accessible on the day of inspection. It is not a warranty of the roof system or of how long it may be watertight. If any conditions are listed a qualified contractor should correct them.

<b>STYLE:</b>	The predominant roof style of the structure.
<b>Type:</b>	Gable
<b>COVERING:</b>	Covering material is partially a matter of taste, but performs the vital function of keeping water out of the structure. The life of roofing material can vary greatly depending on geographic area and estimates of remaining life (if given) are ESTIMATES.
<b>Material:</b>	Asphalt Shingle
<b>Condition:</b>	<b>Roof ok ---</b> Roof appears to be satisfactory, which means it may show evidence of past or present leaks or may soon develop leaks. However, such a roof can be repaired and give generally satisfactory service within the limits of its age.
<b>SEEN FROM:</b>	This section describes the method the inspector used to examine the roof and obviously affect the ability to observe any conditions.
<b>Method:</b>	Binoculars
<b>GENERAL:</b>	
<b>Weather:</b>	Rain
<b>OVERHANG:</b>	Overhang describes soffits and fascia. This area is important for proper ventilation of the roof and water removal.
<b>Fascia:</b>	Metal
<b>Rating:</b>	Acceptable
<b>Soffits:</b>	Vented Soffit
<b>Rating:</b>	Acceptable
<b>DRAINAGE:</b>	This section covers the items used to move the water shed by the roof away from the structure. Water falling too close to the foundation can cause undermining, settlement and leaks into the structure if present.
<b>Type:</b>	Metal
<b>Rating:</b>	Acceptable
<b>Down Spouts:</b>	Metal
<b>Rating:</b>	Acceptable
<b>VENTILATION:</b>	The types and condition of attic ventilation is covered in this section. Proper ventilation is important for maximum life of the roof covering and framing materials.
<b>Type:</b>	Gable, Ridge, Soffit
<b>Rating:</b>	Acceptable
<b>FLUES/VENTS:</b>	Flues are used to vent gases and heat from heating devices and vents are used to vent the plumbing system to atmosphere. This section describes any damage or problems at the roof level.
<b>Plumbing:</b>	Plastic
<b>Rating:</b>	Acceptable

## Foundation / Structure

This inspection is based on observation of the visible portions of the foundation and structure. If any conditions are listed a qualified contractor should correct them.

**FOUNDATION:** This is the support for the primary part of the structure. Therefore, it is very important that the proper material be used and installed. Ventilation is important in order to avoid excessive moisture and resulting structural damage.

**Type:** Frost Walls  
**Rating:** Acceptable

**Materials:** Concrete  
**Rating:** Acceptable

**WALLS:** This section reports on the exterior walls of the building above the foundation and the bulkhead (if any).

**Exterior:** Frame  
**Rating:** Acceptable

CONFIDENTIAL

# Electrical

The following opinion is based on an inspection of the visible portion of the electrical system. If any conditions are listed a qualified electrician should correct them.

**SERVICE:** Exterior service up to and including the meter may be the responsibility of the local power company. If any problems are noted, contact them for repairs or questions.

**Type:** Underground

**Entrance Mat:** Aluminum  
**Rating:** Acceptable

**Ground:** Buried Electrode

**Amps:** 400

**SUB PANELS:** Auxiliary or subpanels are used to extend the system or provide a protected power source near large appliances or equipment. Use the same caution as with the main panel.

**Type:** Breaker  
**Rating:** Acceptable

**Location:** Garage

**Amp Rating:** 100

**Volts:** 120/240

**BRANCH WIRING:** This is the wiring that makes up the bulk of electrical system. Because much of it is hidden by walls, insulation, etc., only the visible portions are examined.

**Type:** Romex  
**Rating:** Acceptable

**Material:** Aluminum, Copper  
**Condition:** **Large aluminum conductors** --- Larger circuits have aluminum conductors. (8 gauge or larger). This is not uncommon. If proper connectors are used at each termination, this type of wiring should not cause any problems.

**Rating:** Acceptable

**INTERIOR COMP:** The inspection covers a representative number of components. The National Electrical Code has extensive regulations concerning interior wiring. If you have any doubt about the system, have it thoroughly inspected by a qualified electrician.

**Receptacles:**  
Condition: **Receipt ok** --- Using a circuit tester, grounding type receptacles were randomly checked and correct wiring was indicated.

**GFI:**  
Condition: **GFCI ok** --- Using a ground fault interrupter (G.F.I.) tester, receptacles checked, indicated a properly functioning G.F.I.

**Detector:**  
Condition: **Smoke detector present** --- Smoke detector(s) were noted. Be sure to check the detector(s) as suggested by manufacturer.  
**No carbon monoxide detector** --- As of 3/6/03 every one and two family home, co-op or condo constructed or offered for sale requires a functioning carbon monoxide detector.

**EXTERIOR COMP:** Exterior components add convenience but have additional hazards because of the presence of water.

**Receptacles:**  
Condition: **GFCI ok** --- Using a ground fault interrupter (G.F.I.) tester, receptacles checked, indicated a properly functioning G.F.I.

CONFIDENTIAL

# Plumbing

The standard inspection report does not include the testing of water salinity, quality or volume of any well supply. Only interior waste systems are inspected. If any conditions are listed a qualified plumber should repair them.

**WASTE/WATER:** This section describes the type of water supply and waste system for the structure.

**Waste Type:** Public

**Water Type:** Public

**MAIN SUPPLY:** This section covers the type and material of the main water supply to each unit. Learn where your shutoff valve is! If a supply line ruptures extensive water damage can occur rapidly.

**Material:** Copper  
**Rating:** Acceptable

**Shutoff:** Closet

**Size:** 3/4"

**SUPPLY PIPING:** This is the potable water used for drinking and cooking needs.

**Piping Mat:** Copper  
**Rating:** Acceptable

**Flow:** Adequate

**WASTE PIPING:** This is the water that is disposed of from toilets, sinks and other plumbing fixtures.

**Piping Material:** Plastic  
**Rating:** Acceptable

**Flow:** Adequate

**HOT WATER:** The hot water supply system is inspected where visible. Interior heating elements (if any) are not examined.

**Type:** Electric

**Condition:** **Relief pipe short ---** Temperature/pressure relief valve extension pipe appears to be missing or too short. This pipe should extend to within 6" above floor level.  
Location: units b & c

**Rating:** Maintenance Required

**Size:** 40

# Heating

The heating system is one of the most important areas in the structure. Improper maintenance may cause uncomfortable heat and fuel bills can be excessively high. If any conditions are listed a qualified heat technician should correct them.

**LOCATION:** All heating equipment should be serviced annually.

**Location:** closet in garage

**WARM AIR:** Warm air systems heat air and distribute it to the living space via ductwork. These systems include gas and oil furnaces as well as heat pumps.

**Furnaces:** Forced Air  
**Condition:** **Fired ok** --- Turned up thermostat, system started and was functional.

**Duct:** Metal  
**Rating:** Acceptable

**Filters:** Disposable  
**Condition:** **Filter dirty** --- System air filters were dirty, and should be cleaned or replaced.  
**Rating:** Maintenance Required

**FUEL:** This section reports the type or types of fuel in use. Most equipment is designed for one type of fuel.

**Fuel Type:** Natural Gas

**Fuel Valve:** at furnace  
**Rating:** Acceptable

**THERMOSTATS:** This section reports the type, location, and the condition of the thermostat for the primary heating system of the structure.

**Type:** Mechanical  
**Rating:** Acceptable

**HEATING FLUES:** This section reports on the type and condition of the heating system flues.

**Type:** Plastic  
**Rating:** Acceptable

## A/C

The inspector examines only central or built in air conditioners. Window units are personal property. If any conditions are listed a qualified technician should correct them.

**UNIT TYPE:** Performance of different air conditioner types varies greatly. Observations are based on comparable units of the same type.

**Type:** Central  
**Condition:** **Clean compressor ---** Compressor is in need of cleaning. No debris should be allowed to accumulate inside or around the compressor.  
**Comments:** Uncover compressors prior to activation.  
**Rating:** Maintenance Required

### EQUIPMENT LOCATION:

All air conditioning equipment should be serviced annually.

**Location:** Exterior

### ELECTRICAL:

**Disconnect:** Weatherproof  
**Rating:** Acceptable

CONFIDENTIAL

# Kitchens

If any conditions are listed in this section a qualified contractor should correct them.

**EXHAUST FANS:** This section describes the type and function of the kitchen exhaust in use.

**Type:** Above Range  
**Rating:** Acceptable

**FLOORING:** The type of floor covering is noted. Normal wear and tear or cosmetic deficiencies are not noted unless significant.

**Type:** Sheet vinyl  
**Rating:** Acceptable

**CABINETS:** The proper amount of cabinets is a matter of personal taste. This inspection is restricted to their overall condition and installation.

**Material:** Wood  
**Rating:** Acceptable

**COUNTERTOPS:** Overall condition and type of countertop(s) are noted in this section.

**Material:** Laminate  
**Rating:** Acceptable

**APPLIANCES:** Appliances are covered in this section with respects to functionality only.

**Not Inspected**

**FIXTURES:** The type and condition of the kitchen fixtures is reported in this section.

**Sink:** Double bowl sink  
**Rating:** Acceptable

## Baths

If any conditions are listed a qualified professional should correct them.

**Tub/Shower:** Tub  
Rating: Acceptable

**Fixtures:** Vanity  
Rating: Acceptable

**Ventilation:** Fan  
Rating: Acceptable

**Toilet:** Water tank type  
Rating: Acceptable

**Floor:** Sheet vinyl  
Rating: Acceptable

CONFIDENTIAL

## Interior / Attic

Cosmetic deficiencies may not be reported on unless they have an impact on habitation or have caused structural damage. If any conditions are listed a qualified contractor should be consulted.

**FLOORS:** Floor covering types and conditions are reported if there are other than cosmetic problems. For example, loose floor covering can be a tripping hazard.

**Type:** Carpet, Sheet vinyl  
**Rating:** Acceptable

**WALLS:** The type, material and integrity of the interior walls are reported on a representative basis only.

**Type:** Drywall  
**Rating:** Acceptable

**CEILINGS:** The type, material and integrity of the ceilings are reported on a representative basis only.

**Type:** Drywall  
**Rating:** Acceptable

**DOORS:** The interior doors are reported on a representative basis.

**Type:** Fiberboard  
**Rating:** Acceptable

**TRIM/HARDWARE:** Trim and hardware are inspected on a representative basis. Lack of hardware is normally only noted if it presents a safety problem such as the inability to easily open a door in case of emergency.

**Trim:** Painted  
**Condition:** **Trim missing** --- Trim is missing and may need to be replaced.  
**Location:** unit d bath base  
**Rating:** Maintenance Required

**RAILS/STAIRS:** Rails and Stairs are inspected in this section. Loose or missing stairs or rails can be hazardous.

**Rails:** Hand rails  
**Rating:** Acceptable

**ATTIC:** The attic is inspected (if possible) for roof support structure, and insulation. Although the attic insulation may be acceptable, the greater the insulating value along with proper attic ventilation and moisture control will lessen the chance of ice dams

**Roof Framing:** Truss  
**Rating:** Acceptable

**Sheathing:** Wafer Board  
**Rating:** Acceptable

**Insulation:** Fiberglass – 9"  
**Rating:** Acceptable

# Wood Destroying Insect Infestation Inspection Report

This is not a structural damage report. This form may not be altered.

Company's Business Lic. \_\_\_\_\_ FHA / VA Case No. (if any): \_\_\_\_\_

## Section I. General Information

Home Inspections, Inc.  
6 Highland Avenue Queensbury, NY 12804  
518-792-4237

93 Spring Street Ext.  
South Glens Falls, NY

Inspector's Name: Tony LoCascio

Structure(s) Inspected: \_\_\_\_\_

**Section II. Inspection Findings** This report is indicative of the condition of the subject structure(s) on the date of the inspection only and is not to be construed as an express or guarantee against latent, concealed, or future infestation or defects. Any such warranty or service agreement to provide future treatment or inspections may be provided as a separate attachment and only if indicated in Section IV. **See Section IX on side 2 for important information.** Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected:

- a. **No Visible** evidence of a wood destroying insect infestation was observed.
- b. **Visible evidence** of a wood destroying insect infestation was observed as follows:
- Live insects: (description and location): \_\_\_\_\_
- Insect parts, frass, exit holes or shelter tubes; (description and location): \_\_\_\_\_
- Damage from wood destroying insects was noted in the following area(s): \_\_\_\_\_

Regarding visible evidence of wood destroying insects: The inspector may find wood which has been damaged by insects. Any damage noted should be considered only as evidence of current or previous infestation of wood destroying insects. If box b is checked above, it should be understood that some degree of damage, including hidden damage, may be present. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair. Upon receipt of this report, the Seller or the Seller's Agent shall notify the Buyer that any damage should be examined by a qualified individual to determine the need for repair.

Any visible evidence observed above appears:

- Active; treatment recommended at this time (Note: FHA and VA require treatment for all active infestations)
- Inactive: no treatment recommended at this time
- Activity and need for treatment cannot be determined without further investigation. Reason: \_\_\_\_\_

In many cases, based upon visible signs of infestation by wood destroying insects, it is not possible without benefit of subsequent inspections and evaluations over a period of time to ascertain whether an infestation is active or inactive. If a warranty or service agreement is in effect, the company which issued the warranty or service agreement should be contacted. If no warranty or service agreement is in effect the inspecting company or another company may provide treatment if requested and permitted by regulations, for an additional fee.

- It appears that the structure(s) or a portion thereof may have been previously treated. Evidence of previous treatment: \_\_\_\_\_

This company can give no assurances with regard to work that may have been previously performed by other companies. The company which treated the property should be contacted by the Buyer for treatment and warranty information.

## Section III. Treatment

was/is scheduled to be performed by the inspecting company:  Yes  No Date: \_\_\_\_\_

Treatment Description: \_\_\_\_\_

## Section IV. Attachments

The following listed attachments are integral parts of this inspection report

## Section V. Obstructions & Inaccessible Areas

The following areas of the structure(s) inspected were obstructed or inaccessible (see item 4 on side 2):

- Basement \_\_\_\_\_
- Crawl Space \_\_\_\_\_
- Main Level \_\_\_\_\_
- Attic \_\_\_\_\_
- Garage \_\_\_\_\_
- Exterior \_\_\_\_\_
- Porch \_\_\_\_\_
- Addition \_\_\_\_\_
- Other \_\_\_\_\_

The inspector may write out inaccessible areas or use the following key.

- |                         |                         |
|-------------------------|-------------------------|
| 1. fixed ceilings       | 12. only visual access  |
| 2. suspended ceilings   | 13. no access beneath   |
| 3. fixed wall covering  | 14. cluttered condition |
| 4. floor covering       | 15. standing water      |
| 5. insulation           | 16. dense vegetation    |
| 6. cabinets or shelving | 17. exterior coverings  |
| 7. stored items         | 18. window well covers  |
| 8. furnishings          | 19. wood pile           |
| 9. appliances           | 20. snow                |
| 10. no access or entry  | 21. unsafe conditions   |
| 11. limited access      |                         |

## Section VI. Additional Comments

(see side 2)

**Section VII. Inspector's Signature:** Neither I nor the company for which I am acting: have had, presently have, or contemplate having any interest in the property.

Signature: \_\_\_\_\_

Certification or Registration No: (if applicable) \_\_\_\_\_

Date of Inspection: \_\_\_\_\_

**Section VIII. Statement of Buyer & Seller:** This report is integral to, and a necessary part of the inspecting company's full disclosure as to the scope and inherent limitations of the inspection and report of finding. It is most important that the interested parties acknowledge this advice. The Seller hereto agrees that all know property history information regarding WDI infestation, damage from infestation, and treatment history has been disclosed to the Buyer.

Signature of  Seller(s)  Owner(s)  
(If refinancing) X

Date: \_\_\_\_\_

The undersigned hereby acknowledges receipt of a copy of this report  
Buyers Signature: X

Date: \_\_\_\_\_

This report must be signed by the Buyer and Seller as applicable. A legible copy of this signature page must be returned to the inspecting company by the person ordering this inspection.

## Summary

### Exterior

#### SIDING/TRIM

##### Siding

Vinyl

**Condition:** Open seam

Location: at pipe entries

**Maintenance Required**

### Plumbing

#### HOT WATER

##### Type

Electric

**Condition:** Relief pipe short

Location: b & c

**Maintenance Required**

### Heating / Fireplace

#### WARM AIR

##### Filters

Disposable

**Condition:** Filter dirty

**Maintenance Required**

### A/C

#### UNIT TYPE

##### Type

Central

**Condition:** Clean compressor

**Comments:** Uncover compressors prior to activation.

**Maintenance Required**

### Interior / Attic

#### TRIM/HARDWARE

##### Trim

Painted

**Condition:** Trim missing

Location: d bath base

**Maintenance Required**